

# Passive House for the Public Glenroy Community Hub

Kieran Leong

(Bldg.Eng)

WSP

TTW



Turner & Townsend





An aerial photograph of a modern, white, angular building with a flat roof covered in solar panels. The building is situated in a suburban neighborhood with many houses and trees. A large, open green lawn in the foreground features a playground with a wooden structure. A road with parked cars runs along the right side of the building. The overall scene is bright and sunny.

DesignInc

**Budget** \$30M  
**Area** 4,533m<sup>2</sup>  
**Opened** May 2022

Photography: Dianna Snape



# Contents

- Building Overview
- Passivhaus:
  - How
- Challenges & Lesson's Learnt
- Once Open\*





DesignInc




Photography: Dianna Snape



## What is a living building?

It is self-sufficient and limits the use of external resources.  
It connects people to light, air, food, nature, and community.

## How we made the Hub a living building:






























**Ground Floor**



**DesignInc**

Function / meeting  
spaces

Neighbourhood  
learning



**First Floor**













↑  
Maker Space  
Recording Studio  
Jain Room  
↓  
Youth Lounge  
Youth Collection







DesignInc

i

Photography: Dianna Snape















Photography: Dianna Snape







**DesignInc**

**Passivhaus**




# **Passivhaus**

- Passivhaus Classic Certified
- 0.6 ACH
- 'Retrofitted' hybrid construction




**Not designed to be a  
Passivehaus building!**







# Timeline





# Retrofitting Passivehaus





## Form Factor

- Normally between 0.5 – 5
- PH aims to achieve 3 or less





Heat Loss Form Factor = Heat Loss Area / Treated Floor Area

**Form Factor = 11,542 / 4533 = 2.54**



# Form Factor




NOTE:

- THERMAL LEGEND**
- R5.59 m<sup>2</sup>.k/W
  - DENOTES EXTERNAL WALL CLADDING:  
R2.56 m<sup>2</sup>.k/W TO BLOCKWORK CLADDING  
R2.63 m<sup>2</sup>.k/W TO WEATHERGROOVE CLADDING
  - R4.0 m<sup>2</sup>.k/W
  - R2.1 m<sup>2</sup>.k/W
  - R2.9 m<sup>2</sup>.k/W
  - R5.59 m<sup>2</sup>.k/W TO ROOF
  - R4.0 m<sup>2</sup>.k/W TO CEILING

- BUILDING SEALING LEGEND**
- SEALED AIRTIGHT BUILDING ZONE

EXCLUDED FROM PH ENVELOPE






[illegible]



**DesignInc**



**Steel**

**Steel**


**Timber**

**Structure**



# Building Envelope


## Timber Structure





# Building Envelope

## Timber Structure




Facade / Roof



# Building Envelope

Timber Structure




Facade / Roof

Insulation



# Building Envelope

Timber Structure



Facade / Roof


Insulation

Structure



# Building Envelope

Timber Structure



Facade / Roof

Insulation


Structure

Air-tightness Membrane



# Building Envelope


Timber Structure





# Building Envelope


Steel Structure + Brick Veneer





# Building Envelope


Steel Structure + Brick Veneer



Schock Isokorb



Novomur Block






**DesignInc**







# Steel Structure





**Schock Isokorb**



# Steel Structure



-  Airtight envelope
-  "warm" structural steel
-  Schock Isokorb (steel thermal break)
-  "cold" structural steel





# Heritage Separation

- Continuous insulation
- Airtight membrane






# Challenges



# Windows

## Blockwork wall details



DD Stage




Schock Isokorb




# Windows

## Blockwork wall details



DD Stage




Schock Isokorb




# Windows

## Blockwork wall details



## 2 WINDOW HEAD DETAIL - BLOCKWORK WALL + SUNSHADE




## Bond beam solution




# Windows

## Blockwork wall details



Blockwork not available in  
required size + finish




## Bond beam solution

## IFC Stage





Aluminium awning  
supported by external  
steel structure




## Final Construction



# Windows


## Blockwork wall details



Secondary Steel Frame  
COLD only


CUT "snaps" Blockwork

Aluminium awning  
supported by external  
steel structure





# Blockwork veneer






# Blockwork veneer





# Airtight membrane

## Steel bracing



No steel bracing considered



# Airtight membrane

Steel bracing



No steel bracing  
considered



# Airtight membrane

Steel bracing





# Plywood

as airtight membrane





# Blower door testing

## Installed window





# Blower door testing

## Installed window

Benefits of component testing before installation  
completed on other components.  
Identified issues and inconsistencies





# Blower door testing







Once the doors open



Who?



Early Years staff 15



Maternal Child Health Nurses 5



Community Health staff 10



Library staff 30



Council Customer Service 30



Public 300+



DesignInc

Thankyou



Photography: Dianna Snape